Customer License Instructions:

1. Copy the demo license from the install folder (c:\CompassCDS\Client\ScionDemo.lic) to a temporary location, as backup.
2. Delete the ScionDemo.lic file from the install folder.
3. Copy the new license file (*.lic) to the install folder.
4. To ensure the license is recognized, launch the Settings dialog from the Hydrocarbon Reporting Plugin.